

Message Text

UNCLASSIFIED

PAGE 01 SANTO 04524 180300Z
ACTION SY-05

INFO OCT-01 ARA-14 ISO-00 /020 W
-----015792 190122Z /62
R 171940Z AUG 78
FM AMEMBASSY SANTO DOMINGO
TO SECSTATE WASHDC 5715
INFO AMEMBASSY PORT AU PRINCE

UNCLAS SANTO DOMINGO 4524

FOR: A/SY/OPS/T

E.O. 11652: N/A
TAGS: ASEC
SUBJECT: SECURITY NEEDS

RSO RECENTLY READ TECHNICAL SERVICES REPORT FOR DUTIES PERFORMED AT PORT-AU-PRINCE AND SANTO DOMINGO. TSO EXPLAINED DURING SANTO DOMINGO VISIT THAT HE WAS WORKING UNDER COMPRESSED TIME FRAME. AS A RESULT HE WAS NOT ABLE TO MONITOR WORK COMPLETED TO ACCESS CONTROL DOORS AT CONSULAR SECTION; ELECTRICAL BYPASS SYSTEM FAILED SHORTLY AFTER HE LEFT. ALTHOUGH IT IS RECOGNIZED THAT TSO'S ARE UNDER TIGHT SCHEDULE, WOULD APPRECIATE ANOTHER VISIT FOR FOLLOWING WORK WHICH NEEDS GUIDANCE AND ATTENTION:

1. ELECTRICAL BYPASS TO DOORS LEADING TO LIMITED ACCESS AREA FROM LOBBY. (CHANCERY SANTO DOMINGO)
2. AT LEAST TWO DAY MONITORING OF ACCESS DOORS TO CONSULATE WITH ATTEMPT TO ASCERTAIN PROBLEM CAUSING CONTINUING MALFUNCTION. (WE HAVE NO LOCAL SOURCES WHICH MAY ASSIST WITH THIS).
3. JOINT RSO/TSO TRAVEL TO PORT-AU-PRINCE TO CONDUCT SURVEY OF NIV OUTER AREA FOR CCTV CAMERA INSTALLATION AND TO RELOCATE CAMERA IN IMMIGRANT WAITING LOUNGE (RECENT INCIDENT INDICATED CAMERA NEEDS RELOCATING).

UNCLASSIFIED

UNCLASSIFIED

PAGE 02 SANTO 04524 180300Z

4. ADVICE ON NEW MINIMUM STANDARDS CONCEPT TO BE APPLIED CHANCERY ACCESS POINT. (AS IT RELATES TO LOCKING DEVICES AND EXPANSION OF MSG BOOTH TO ACCOMMODATE CCTV CAMERA CONDUITING.)
YOST

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 17 aug 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 jan 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978SANTO04524
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780339-0176
Format: TEL
From: SANTO DOMINGO
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780853/aaaabshk.tel
Line Count: 60
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 80a0fc61-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 13 jun 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 1708765
Secure: OPEN
Status: NATIVE
Subject: SECURITY NEEDS RSO RECENTLY READ TECHNICAL SERVICES REPORT FOR DUTIES PERFORMED AT PORT-AU-PRINCE AND SANTO DOMINGO. TSO EXPLAINED
TAGS: ASEC
To: STATE
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/80a0fc61-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014